Work Orde May 25, 2010 1	er ID 59038 0:33:51 AM										Page 1
Item ID: Revision ID:	D412-702-117B	· · · · · · · · · · · · · · · · · · ·		Accept				Setup	Start		
Item Name: Start Date: Required Date: Reference:		Qty: 1.00 d Qty: 1.00	1 1 1 1 1 1 1 1 1 1		Cust Item ID: Customer:	:			Stop		
Approvals:	Process Plan:		Date:	Tooling: SPC (Y/N):	Date			Run	Start Stop		
Sequence ID/ Work Center II	Opera D Descr			Set Up/ Run Hours		Draw Pla Rev. Co		pt Re Qt		Reject Number	Insp. Stamp
Draw Nbr 100 Small Fab Small Fab	Revision N	Мето	Der dwg ICA D412-702	0.00 p.49	, 10/05/25			Ď			»
QC Quality Control	QC5- lı	nspect part comple Memo	teness to step on W/O	0.00	wlster			<u> </u>	·		,
120 Packaging Packaging		Memo Identify with CHG001 Location: PPP Rev:	P/N & CHG# and pack	0.00 0.00 for shipping as per PPP I	D412-702-117B		/	for the second) <u> </u>	5 (

Work Order ID 59038

May 25, 2010 10:33:51 AM



Page 2

Item ID:

D412-702-117B

Accept

Setup Start



Revision ID:

Item Name:

Harness Assembly

Start Date:

5/25/10

Start Qty: 1.00 Req'd Qty: 1.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: _____

Date:

Tooling:

Date:

Run

Start

Stop



Required Date: 5/25/10

QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/

Work Center ID

Description

Operation

Set Up/ **Run Hours** 0.00

Draw Number Draw Rev.

Plan Accept Qty Code

Reject Qty

Reject Number Stamp

Insp.

130

QC

Quality Control

Memo

QC21- Final Inspection - Work Order Release

0.00

____10/05/25° \$\int_{10-5-25}^{\int_{10}}

Picklist Print

May 25, 2010 10:33:50 AM

Work Order ID: 59038

Parent Item:

D412-702-117B

Parent Item Name:

Harness Assembly

IPP rev A 07.05.10 new issue EC



Start Date: 5/25/10

Required Date: 5/25/10

Start Qty: 1.00

Required Qty: 1.00

	IPP rev A 07.05.10 IPP Rev:B Removed		7-07-0	6 JLM				S	tart Qty: 1.00)	Required	d Qty: 1.00
Component Item ID/ Item Name AN960JD10LL Washer	Replacement Item ID	Mfg/ Purch Purchased		Primary Location	Last Location	Route Seq ID 100	Unit of Measure Each		Qty per Kit	Total Otv 4	Qty Issued	Date Status Issued
				<u>Location</u> ST349	<u>n</u> 19085 19600		Oty 4431 472 3959	Loc Code	_	Ц	- - Sp	10/05/25 (
D3573-5		Manufactured	No			100	Each	47.0000	1	1		
				<u>Location</u> ST244	<u>n</u> 31863	<u>Loc</u>	<u>Oty</u> 47 47	Loc Code	_	1	- S	10/05/28 6
D3579-045 Shoulder Harness		Manufactured	No			100	Each	2.0000		1		
				Location ST272A	_	Loc	Oty 2 2	Loc Code	_	,	, - Sa	5 10/05/25
K62		Purchased	No			100	Each	35.0000	1	1		
				<u>Location</u> ST243A	_	<u>Loc</u>	Oty 35 1 34	Loc Code	<u>-</u> -		- - St	10/05/250

Picklist Print

May 25, 2010 10:33:50 AM

Work Order ID: 59038

Parent Item:

D412-702-117B

Parent Item Name:

Harness Assembly

Comments:

IPP rev A 07.05.10 new issue EC

IPP Rev:B Removed Decal D3569 07-07-06 JLM



Start Date: 5/25/10

Required Date: 5/25/10

Start Qty: 1.00

Required Oty: 1.00

Component Item ID/ Item Name MS21042L3

Replacement Mfg/ Item ID

Purch Purchased

Bin Primary Item Location No

Last Location Route Seq ID 100

Unit of Measure Each

Qty on Hand 1,810.000

Loc Code

Qty per Kit Total

Otv 4

Qty Date Issued Issued

Status

Page 2

Nut

Location	Loc Qty				
ST300	1810				
113537	20				
113644	290				
114523	1000				

114718 500 100 Each

4 Sp 10/05/25 (1)

MS24693-S272

Purchased

No


217.0000

Loc Code


Screw

Location .	Loc Oty
ST288 .	217
111548	1
112492	216

Sp 10/05/25 0



<u>DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-117A AND</u> <u>D412-702-101B/-103B/-105B/-107B/-109B/-115B/-117B HARNESS ASSEMBLIES</u> (BELTS, K6.2 CLIP AND D3569-1/-2/-3 DECAL NOT SHOWN)



<u>DETAIL 'L' D412-702-111A/-111B/-113A/-113B HARNESS ASSEMBLIES</u> (BELTS AND D3569-1/-2/-3 DECALS NOT SHOWN)

• COPYRIGHT © 2004 BY DART AEROSPACE LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

25-00-00